Accident / Incident Report Closed



							-		
Unit/Department	Process Area		Site			Repo	ort Numbe	er .	
South Operation-Elyria			ELYRIA		0084-SOPS-13-0145				
Report Date	Incident Date		Incident Time		Copi	Copied From			
09/23/2013	09/23/2013		08:00 PM		• • • • • • • • • • • • • • • • • • • •				
Incident Location	/	Team Leader / Supervisor		Repo	Reported By				
Building 31 on first floor.			Dennis Lucas		Thor	Thomas Kurucz			
Title of Event (Limit to 90 cl	The Art of Markette do Hill Provider and the WATER and and	Category				Division / Bus. Group / Subgroup Code			
Detection of NOx on first f	1.		Safety & Health Environmental			CC / G-CCP			
Incident Classification									
Near Miss	Prop	erty Loss		С	ontractor				
Process Safety		ion / NOV				Injury / Illne	SS		
☐ Injury / Illness		th Exposure				ury / Illness			
Spill / Release		ection			5M	,			
Permit / Regulatory Devi	_ •	r Incident			ant Upset				
Fire		Occupational			•	gement Sys	tem Failu	ıre	
Odor Complaint	RMF				her	,,.			
Describe Event / What Happ	i her H i herberg				······				
After we discovered end p			allad Tam I		la alta di a		.1.4 4.11	0.00 11	
also improperly installed v	vith gaps and the	impropeny instr bolts were in bu	aned, Tom r It not tight.	There v	looked a Nas a co	nt the end p Instant NO	olate ot # c release	of 2.9.	as
Immediate Corrective Action									.,
We stopped the feed, close properly reinstalled.	ed the slide gate,	then started to i	oring tempe	ratures	down s	o that the	back plat	e could b	е
Immediate Cause									
Improper installation of ba	ick plate on #2 RC	· · · · · · · · · · · · · · · · · · ·				·····			
Spill Release Type(s)	Non RQ Spill /	Release							
Chemical(s) Involved	j redicted Optil 2	CAS#	Phy.	State	Аіг	Land	Water	Contmt	Units
Nitrogen Dioxide (NOx)		10102-44-0	Gas		.9	0	0	0	lbs
Disposition of Material	Disperse in air			1.7 N					I IDS
Weather Conditions	Skies:	Temne	erature:		l Wi	nd Direction		Wind Sp	eed
			riature.					VIII.G OF	
Cause Narrative			- 1 - 5 vila - 5 5 5 5 5						
Plate was improperly insta	lled allowing NOx	to escape from	the calcine	r.					
Contributing Causes		Root/Primary							
Operator did not take the time to properly install 208 - Personal 208									
the plate on the calciner. Performance Performance									
No procedure exists for job s includes walking the line to e set-up.	111 - Procedu	res 112	112 - Not Used		116 - No Procedure for Task				
Current JSP does not address removing and replacing the back plate on the calciner.		111 - Procedu		130 - Wrong/Incomplete		136 - Inco Covered	136 - Incomplete/Situation Not Covered		
Explanation of Root Causes									
· · · · · · · · · · · · · · · · ·									
111/112/116 - Walking the No procedure exists for ch			vould have	identifi	ed issue	with impr	operly in:	stalled pla	ate.

Printed: 09/29/2016

Page: 1

111/130/136 - Current JSP for cleaning out the calciner does not included removing or replacing the plates. It also does not reference inspecting the calciner after cleaning.

Any known or potential off-site impacts? | No. | PSM Incident? | No. | Estimated Cost: | 100 00 USD |

		No	PSM Incident?	No	Estimated Co	ost: 100.00	USD	
		Justin Quach; Gregory A Menz; Dennis Lucas; Thomas Kurucz; William Grodecki; Jennifer Bailey						
lte m	Corrective Action(s) to prevent recur	rence	e Responsible Person		Target Date	Final Closed Date	VC Re q	VE Re q
1	C: Modify existing JSP to include removing, replacing, and inspecting back plate on calciner.		Thomas Kurucz/BASF-CATALYSTS/BASF		12/31/2013	06/26/2014	N	N
2	C: Assist J. Bodmann in developing a job start-up (walking the line) checklist. Refer to action item from AIM - SOPS -161		Thomas Kurucz/BASF-CATALYSTS/BASF		11/30/2013	03/03/2014	N	N
3	C: 5S of calciner area		Jennifer Bailey/BASF-CATAL	YSTS/BASF	06/30/2014	06/23/2014	N	N

	Approved By:		
	Manager / Dept. Head	Leon Zavodnik 11/20/2013 07:32 AM	
ĺ	EHS Unit Coordinator	Jason M Therrien 10/31/2013 01:55 PM	 The second secon
ĺ	Employee	Dennis Lucas 07/16/2014 06:21 AM	
L.			

Printed: 09/29/2016